

Inspection Photos
Location Name: Lilli Unit #14-5
Location ID: 323731



Photo 1: Location



Photo 2: Wellhead

Inspection Photos
Location Name: Lilli Unit #14-5
Location ID: 323731



Photo 3: Unused hose by treater house



Photo 4: Weeds in tank battery, on berm

Inspection Photos
Location Name: Lilli Unit #14-5
Location ID: 323731



Photo 5: No capacity on water vault sign.

