

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/12/2018

Submitted Date:

06/13/2018

Document Number:

689401376

**FIELD INSPECTION FORM**

Loc ID 334445 Inspector Name: CONKLIN, CURTIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1401 SEVENTEENTH STREET #1400  
City: DENVER State: CO Zip: 80202

**Findings:**

15 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

| Contact Name       | Phone | Email                                 | Comment                         |
|--------------------|-------|---------------------------------------|---------------------------------|
| Laramie Energy LLC |       | cogccnotifications@laramie-energy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 244         | WELL | PR     | 08/18/2009  | GW         | 077-09480 | GRIFFITH 11-1C | PR          |
| 245         | WELL | SI     | 02/01/2017  | GW         | 077-09481 | GRIFFITH 11-1B | PR          |
| 294746      | WELL | PR     | 03/01/2012  | GW         | 077-09511 | GRIFFITH 11-8B | PR          |
| 294747      | WELL | PR     | 11/18/2008  | GW         | 077-09512 | GRIFFITH 11-8A | PR          |
| 297161      | WELL | PR     | 04/02/2010  | GW         | 077-09676 | GRIFFITH 11-7A | PR          |
| 297162      | WELL | PR     | 04/04/2010  | GW         | 077-09677 | GRIFFITH 11-7B | PR          |
| 297163      | WELL | PR     | 04/17/2010  | GW         | 077-09678 | GRIFFITH 11-2C | PR          |
| 297164      | WELL | PR     | 04/19/2010  | GW         | 077-09679 | GRIFFITH 11-2B | PR          |
| 297165      | WELL | PR     | 07/17/2013  | GW         | 077-09680 | GRIFFITH 11-1A | PR          |
| 297166      | WELL | PR     | 04/08/2015  | GW         | 077-09681 | GRIFFITH 11-2A | PR          |
| 297167      | WELL | PR     | 12/02/2013  | GW         | 077-09682 | GRIFFITH 11-7C | PR          |

**General Comment:**

[This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment: [Posted Emergency Contact Number 1-970-248-0497](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| METHANOL           | 1 | <50 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents   | # | Capacity | Type      | Tank ID | SE GPS |
|------------|---|----------|-----------|---------|--------|
| CONDENSATE | 7 | 300 BBLS | STEEL AST |         | ,      |

|                    |  |       |
|--------------------|--|-------|
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    |       |  |
|                    |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |   |       |      |             |           |         |       |               |    |
|-----------------------|---|-------|------|-------------|-----------|---------|-------|---------------|----|
| Facility ID:          | 244   | Type: | WELL | API Number: | 077-09480 | Status: | PR    | Insp. Status: | PR |
| <b>Producing Well</b> |   |       |      |             |           |         |       |               |    |
| Comment:              | PR w/ Plunger                                       |       |      |             |           |         |       |               |    |
| Corrective Action:    |   |       |      |             |           |         | Date: |               |    |
| Facility ID:          | 245   | Type: | WELL | API Number: | 077-09481 | Status: | SI    | Insp. Status: | PR |
| <b>Producing Well</b> |   |       |      |             |           |         |       |               |    |
| Comment:              | Well appeared to be producing at time of inspection |       |      |             |           |         |       |               |    |
| Corrective Action:    |   |       |      |             |           |         | Date: |               |    |
| Facility ID:          | 294746  | Type: | WELL | API Number: | 077-09511 | Status: | PR    | Insp. Status: | PR |
| <b>Producing Well</b> |   |       |      |             |           |         |       |               |    |
| Comment:              | PR w/ Plunger                                       |       |      |             |           |         |       |               |    |
| Corrective Action:    |   |       |      |             |           |         | Date: |               |    |
| Facility ID:          | 294747  | Type: | WELL | API Number: | 077-09512 | Status: | PR    | Insp. Status: | PR |
| <b>Producing Well</b> |   |       |      |             |           |         |       |               |    |
| Comment:              | PR w/ Plunger                                       |       |      |             |           |         |       |               |    |
| Corrective Action:    |   |       |      |             |           |         | Date: |               |    |
| Facility ID:          | 297161  | Type: | WELL | API Number: | 077-09676 | Status: | PR    | Insp. Status: | PR |
| <b>Producing Well</b> |   |       |      |             |           |         |       |               |    |
| Comment:              | PR w/ Plunger                                       |       |      |             |           |         |       |               |    |
| Corrective Action:    |   |       |      |             |           |         | Date: |               |    |
| Facility ID:          | 297162  | Type: | WELL | API Number: | 077-09677 | Status: | PR    | Insp. Status: | PR |
| <b>Producing Well</b> |   |       |      |             |           |         |       |               |    |
| Comment:              | PR w/ Plunger                                       |       |      |             |           |         |       |               |    |
| Corrective Action:    |   |       |      |             |           |         | Date: |               |    |
| Facility ID:          | 297163  | Type: | WELL | API Number: | 077-09678 | Status: | PR    | Insp. Status: | PR |
| <b>Producing Well</b> |   |       |      |             |           |         |       |               |    |
| Comment:              | PR w/ Plunger                                       |       |      |             |           |         |       |               |    |
| Corrective Action:    |   |       |      |             |           |         | Date: |               |    |
| Facility ID:          | 297164  | Type: | WELL | API Number: | 077-09679 | Status: | PR    | Insp. Status: | PR |
| <b>Producing Well</b> |   |       |      |             |           |         |       |               |    |
| Comment:              | PR w/ Plunger                                       |       |      |             |           |         |       |               |    |
| Corrective Action:    |   |       |      |             |           |         | Date: |               |    |

|  |                   |                              |                   |                         |
|--|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>297165</u>             | Type: <u>WELL</u> | API Number: <u>077-09680</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| <b><u>Producing Well</u></b>           |                   |                              |                   |                         |
| Comment: <a href="#">PR w/ Plunger</a> |                   |                              |                   |                         |
| Corrective Action:                     |                   | Date:                        |                   |                         |
| Facility ID: <u>297166</u>             | Type: <u>WELL</u> | API Number: <u>077-09681</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| <b><u>Producing Well</u></b>           |                   |                              |                   |                         |
| Comment: <a href="#">PR w/ Plunger</a> |                   |                              |                   |                         |
| Corrective Action:                     |                   | Date:                        |                   |                         |
| Facility ID: <u>297167</u>             | Type: <u>WELL</u> | API Number: <u>077-09682</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| <b><u>Producing Well</u></b>           |                   |                              |                   |                         |
| Comment: <a href="#">PR w/ Plunger</a> |                   |                              |                   |                         |
| Corrective Action:                     |                   | Date:                        |                   |                         |

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [Stormwater erosion appears to be controlled on the location at this time.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description              | URL   |
|--------------|--------------------------|---|
| 689401377    | Griffith 11-2 Pad Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4493413">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4493413</a> |