

**Inspection Photo  
Frei A-12  
API # 045-19949  
Inspection # 689301301**



**Location Photo #1,**



**Location Photo #2, Wellhead sign not legible**



**Inspection Photo**  
**Frei A-12**  
**API # 045-19949**  
**Inspection # 689301301**



**Location Photo #3, Spilled condensate in drip pan**



**Location Photo #4, Stained rock in tank battery containment**



**Inspection Photo**  
**Frei A-12**  
**API # 045-19949**  
**Inspection # 689301301**



**Location Photo #5, Stained rock in tank  
battery containment**



**Location Photo #6, Stained rock in tank  
battery containment**

**Inspection Photo**  
**Frei A-12**  
**API # 045-19949**  
**Inspection # 689301301**



**Location Photo #7, Stained rock in tank battery containment**



**Location Photo #8, Tank sign not legible**