

Final Reclamation and Stormwater Inspection

June 7, 2018

Operator: MARTIN OIL SERVICE INC – 54200

Location ID: 336426

Inspection Document #: 674902193

Weld County, CO

NWSW Section 24 T2N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: MARTIN OIL SERVICE INC /2N68W24

Location ID: 336426



Photo 1. Photo taken from the well location, facing South. Location was not constructed at the proposed well location based off field observations and an aerial imagery assessment.