

# *Inspection Photos*

*Loc#429897*

*Operator: GRMR*

*Inspection Number: 674104466*

*Inspection Date: 5/25/2018*





Photo#1:  
Overview of Location to Northwest.

May 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: GRMR Hamilton Loc#429897



Photo#2:

View to West along South edge of Location.

May 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: GRMR Hamilton Loc#429897



Photo#3:  
View over Location June 7, 2018.

June 7, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: GRMR Hamilton Loc#429897