



Photo#1:  
Overview of Location to Southeast.

May 17, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Berry Chevron C 12 Loc#336001



Photo#2:  
Vegetation is emerging across Location..

May 17, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Berry Chevron C 12 Loc#336001



Photo#3:  
Vegetation is emerging across Location..

May 17, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Berry Chevron C 12 Loc#336001