

Final Reclamation and Stormwater Inspection

June 13, 2018

Operator: NOBLE ENERGY PRODUCTION INC – 10120

Location ID: 409042

Inspection Document #: 674902214

Weld County, CO

SWSE Section 27 T3N R62W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: NOBLE ENERGY PRODUCTION INC/3N61W32

Location ID: 409042



Photo 1. Photo taken from the access road looking towards the well location, facing East. Appears the Operator has not performed any reclamation activities on the access road itself but has on the well pad location.



Photo 2. Photo taken from the well location, facing North. The reclamation operations have failed to generate perennial vegetation cover. Disturbance area is currently dominated by the annual List C Colorado Noxious Weed cheatgrass.

Inspection Photos

Location Name: NOBLE ENERGY PRODUCTION INC/3N61W32

Location ID: 409042



Photo 3. Photo taken from the well location, facing Northeast. See comments from Photo 1.



Photo 4. Photo taken from the well location, facing Southwest. See comments from Photo 1.

Inspection Photos

Location Name: NOBLE ENERGY PRODUCTION INC/3N61W32

Location ID: 409042



Photo 5. Photo taken from the adjacent reference area., facing North. Showing dominant perennial grass cover, needle and thread grass. See comments under Photo 2.



Photo 6. Photo taken from the adjacent reference area, facing West. Showing dominant perennial grass cover, needle and thread grass. See comments under Photo 2.