

PHOTO: VIEW OF EXISTING WELL

CAMERA ANGLE: EASTERLY



PHOTO: VIEW FROM BEGINNING OF EXISTING ACCESS

CAMERA ANGLE: SOUTHWESTERLY

TEP Rocky Mountain LLC

**GV 33-22 REMOTE FRAC PAD
SW 1/4 SE 1/4, SECTION 22, T7S, R96W, 6th P.M.
GARFIELD COUNTY, COLORADO**



UELS, LLC
Corporate Office * 85 South 200 East
Vernal, UT 84078 * (435) 789-1017

TAKEN BY	C.R.	01-17-18	
DRAWN BY	Z.T.	04-19-18	
LOCATION PHOTOS			PHOTO 1



PHOTO: VIEW OF EXISTING WELLS

CAMERA ANGLE: NORTHERLY



PHOTO: VIEW OF EXISTING WELLS

CAMERA ANGLE: WESTERLY

TEP Rocky Mountain LLC

**GV 33-22 REMOTE FRAC PAD
 SW 1/4 SE 1/4, SECTION 22, T7S, R96W, 6th P.M.
 GARFIELD COUNTY, COLORADO**



UELS, LLC
 Corporate Office * 85 South 200 East
 Vernal, UT 84078 * (435) 789-1017

TAKEN BY	C.R.	01-17-18	
DRAWN BY	Z.T.	04-19-18	
LOCATION PHOTOS			PHOTO 2



PHOTO: VIEW OF EXISTING WELLS

CAMERA ANGLE: SOUTHERLY




PHOTO: VIEW OF EXISTING WELL

CAMERA ANGLE: EASTERLY

TEP Rocky Mountain LLC

**GV 33-22 REMOTE FRAC PAD
SW 1/4 SE 1/4, SECTION 22, T7S, R96W, 6th P.M.
GARFIELD COUNTY, COLORADO**



UELS, LLC
Corporate Office * 85 South 200 East
Vernal, UT 84078 * (435) 789-1017

TAKEN BY	C.R.	01-17-18	
DRAWN BY	Z.T.	04-19-18	
LOCATION PHOTOS			PHOTO 3