

# Inspection Photos

06/15/2018

Operator: FOUNDATION ENERGY  
MANAGEMENT LLC - 10112

Location ID: 327558

Inspection Doc. Number: 682503501  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 327558



**Photo 1:** Photo of well/sign



**Photo 2:** Photo taken from the northwest end of the location, facing southwest. Photo of Diffuse Knapweed observed along access road and interim area.

Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 327558



**Photo 4:** Photo taken from the northeast end of the location, facing southwest. Photo of Diffuse Knapweed observed along access road and interim area.



**Photo 4:** 2013 Aerial imagery. Photo shows areas (red polygon) where Noxious Weeds (Diffuse Knapweed) were observed on location and access road, and mapped using a GPS.