

Inspection Photo
Benjamin Fed 28-13C2 (K28NW)
API # 045-20179
Inspection # 689301333



Location Photo #1



Location Photo #2



Inspection Photo
Benjamin Fed 28-13C2 (K28NW)
API # 045-20179
Inspection # 689301333



**Location Photo #3, Weeds behind Vessels
next to rock wall**



**Location Photo #4, weeds west of the
battery containments**

Inspection Photo
Benjamin Fed 28-13C2 (K28NW)
API # 045-20179
Inspection # 689301333



**Location Photo #5, weeds north west corner
of battery containment**



Location Photo #6, weeds near wellheads

Inspection Photo
Benjamin Fed 28-13C2 (K28NW)
API # 045-20179
Inspection # 689301333



Location Photo #7, Stained rock in between tanks in battery containment



Location Photo #8, Stained rock in between tanks in battery containment

Inspection Photo
Benjamin Fed 28-13C2 (K28NW)
API # 045-20179
Inspection # 689301333



Location Photo #9, Stained rock in between tanks in battery containment



Location Photo #10, Stained rock in between tank battery containment