

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Jun 5, 2018 3:10:35 PM MDT
Server Receive Date:	Jun 5, 2018 3:44:24 PM MDT
Reference Number:	20180605-1880147892
Location:	2484 Co Rd 222, Durango, CO 81303, USA Jun 5, 2018 3:07:45 PM MDT [View Map]

Information

Name	celkins@gobrainstorm.net
Date	May 30, 2018
Well Name	DAVIS, FRANK GAS UNIT B 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Grading/recontour Seeding Erosion Repairs Install Rock Run Down Repaired Berm Grading of Road Removed sediment from BMP's

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos

