

Inspection Photos

Location Name: Krier 4 Land Application Site, Facility: 454282

Inspection Date: 06/19/2018



Photo 1 – From north end of Krier 4 Land Application Area at Carlson 22-1 tank battery looking southeast toward the Carlson 22-1 well.



Photo 2 – From north end of Krier 4 Land Application Area at Carlson 22-1 tank battery looking west. Ditches have been cut on the north end of the land application area to aid in stormwater control.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Krier 4 Land Application Site, Facility: 454282

Inspection Date: 06/19/2018



Photo 3 – From north end of Krier 4 Land Application Area at Carlson 22-1 tank battery looking west.



Photo 4 – At the northwest end of the Krier 4 Land Application Area. Stormwater ditches lead to a stormwater detention pond.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Krier 4 Land Application Site, Facility: 454282

Inspection Date: 06/19/2018



Photo 5 – At DCP compressor station on County Road 68 and 91. Looking east at vacuum truck performing liquid recovery.



Photo 6 – At DCP compressor station on County Road 68 and 91. Looking southwest.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Krier 4 Land Application Site, Facility: 454282

Inspection Date: 06/19/2018



Photo 7 – On County Road 68, 1/4 mile west of County Road 91. Looking west toward DCP station.



Photo 8 – On County Road 68, 1/4 mile west of County Road 91. Looking south.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources