

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/19/2018

Submitted Date:

06/19/2018

Document Number:

689701493

**FIELD INSPECTION FORM**

Loc ID 335924 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

14 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292776	WELL	PR	01/08/2009	GW	045-14767	CHEVRON TR 34-16-597	PR
292794	WELL	PR	01/08/2009	GW	045-14774	CHEVRON TR 434-16-597	PR
292795	WELL	PR	01/08/2009	GW	045-14773	CHEVRON TR 433-16-597	PR
292796	WELL	PR	01/08/2009	GW	045-14772	CHEVRON TR 334-16-597	PR
292797	WELL	PR	01/08/2009	GW	045-14771	CHEVRON TR 533-16-597	PR
292798	WELL	PR	01/08/2009	GW	045-14770	CHEVRON TR 33-16-597	PR
292799	WELL	PR	01/08/2009	GW	045-14769	CHEVRON TR 534-16-597	PR
292800	WELL	PR	01/08/2009	GW	045-14768	CHEVRON TR 343-16-597	PR
293727	WELL	PR	01/08/2009	GW	045-15121	CHEVRON TR 331-21-597	PR
293728	WELL	PR	01/08/2009	GW	045-15122	CHEVRON TR 431-21-597	PR
414585	PIT	AC	04/19/2010		-	CHEVRON TR 34-16-597 PAD	AC

**General Comment:**

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:			
Corrective Action			Date:
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	970-285-9377		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Type	SEPARATOR		
Comment:			
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Chemical containers at wells		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 16		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		39.609140,-108.279390
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	8	400 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	292776	Type:	WELL	API Number:	045-14767	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	292794	Type:	WELL	API Number:	045-14774	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	292795	Type:	WELL	API Number:	045-14773	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	292796	Type:	WELL	API Number:	045-14772	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	292797	Type:	WELL	API Number:	045-14771	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	292798	Type:	WELL	API Number:	045-14770	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	292799	Type:	WELL	API Number:	045-14769	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	292800	Type:	WELL	API Number:	045-14768	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: <u>293727</u>	Type: <u>WELL</u>	API Number: <u>045-15121</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment:	<u>Producing well</u>			
Corrective Action:			Date:	
Facility ID: <u>293728</u>	Type: <u>WELL</u>	API Number: <u>045-15122</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment:	<u>Producing well</u>			
Corrective Action:			Date:	
Facility ID: <u>414585</u>	Type: <u>PIT</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Culverts	Pass			
		Compaction	Pass			
Compaction	Pass					
		Ditches	Pass			
		Gravel	Pass			
Ditches	Pass					
				Material Handling And Spill Prevention	Pass	
		Check Dams	Pass			
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: \_\_\_\_\_ Lined: \_\_\_\_\_ Pit ID: 414585    Lat: 39.609260    Long: -108.278900

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action:

Date: c

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment: Pit has been closed.

Corrective Action:

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689701494	Inspection 689701493 photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4500952">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4500952</a>