

# Final Reclamation and Stormwater Inspection

June 14, 2018

Operator: PDC ENERGY INC – 69175

Location ID: 323254

Inspection Document #: 674902238

Weld County, CO

NWNE Section 24 T2N R68W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: PDC Energy /2N68W24  
Location ID: 323254



**Photo 1.** Photo taken from the location. Appears the location was mowed but patches of Canada thistle still remain that were missed in the mowing process.



**Photo 2.** Photo taken from the location showing Canada thistle that was mowed but flowers remain.