

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/31/2018

Submitted Date:

06/11/2018

Document Number:

688400195**FIELD INSPECTION FORM**Loc ID 319094 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------------------|---------|
| , | | COGCCInspections@extracti onog.com | |
| Adamczyk, Megan | | megan.adamczyk@state.co.u s | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 453223 | WELL | DG | 02/05/2018 | | 123-45983 | Coyote Trails 34S-20-12N | WO |
| 453224 | WELL | DG | 02/04/2018 | | 123-45984 | Coyote Trails 34S-20-14C | WO |
| 453227 | WELL | DG | 02/03/2018 | | 123-45987 | Coyote Trails 34S-20-15N | WO |
| 453230 | WELL | DG | 02/03/2018 | | 123-45990 | Coyote Trails 34S-20-16N | WO |
| 453231 | WELL | DG | 02/05/2018 | | 123-45991 | Coyote Trails 34S-20-11C | WO |
| 453233 | WELL | DG | 02/04/2018 | | 123-45993 | Coyote Trails 34S-20-13N | WO |
| 453234 | WELL | DG | 02/06/2018 | | 123-45994 | Coyote Trails 34S-20-10N | WO |

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------|-------|--|
| Type | OTHER | | |
| Comment: | Fracking | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | |
| Corrective Action: | | Date: _____ |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|--|-------|--|
| Type | LOCATION | | |
| Comment: | Approx 32' sound walls on west and south end of location | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

| | | | | |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>453223</u> | Type: <u>WELL</u> | API Number: <u>123-45983</u> | Status: <u>DG</u> | Insp. Status: <u>WO</u> |
| Facility ID: <u>453224</u> | Type: <u>WELL</u> | API Number: <u>123-45984</u> | Status: <u>DG</u> | Insp. Status: <u>WO</u> |
| Facility ID: <u>453227</u> | Type: <u>WELL</u> | API Number: <u>123-45987</u> | Status: <u>DG</u> | Insp. Status: <u>WO</u> |
| Facility ID: <u>453230</u> | Type: <u>WELL</u> | API Number: <u>123-45990</u> | Status: <u>DG</u> | Insp. Status: <u>WO</u> |
| Facility ID: <u>453231</u> | Type: <u>WELL</u> | API Number: <u>123-45991</u> | Status: <u>DG</u> | Insp. Status: <u>WO</u> |

Complaint

Comment: [Field Inspector Assigned: Jason E. Gomez](#)

[Complaint Received:](#)

[Date: 5-31-2018](#)

[Complaint Contacted:](#)

[Date: 5-31-2018 Time 1540 Hrs](#)

[Location #: 319094](#)

[Inspection Document #: 688400195](#)

[Nature of complaint: Noise](#)

[Field Inspector Actions:](#)

[On 5-31-2018, I was contacted by COGCC staff in reference to some complaints received by the COGCC in reference to noise, the complaint stated the noise was coming from the Erie area originating from the Extraction, Coyote location.](#)

[On 5-31-2018, I attempted to contact the complaints in reference to the noise she was experiencing which she perceived as coming from the Coyote fracking location. I performed a complete site inspection of the Coyote location. I reviewed location records, which did not show any abnormal fracking conditions at the time of the complaints. I reviewed third party sound records at the times of the complaint and at no time did the drilling operation exceed COGCC rules according to the sound study information reviewed.](#)

[No violation of COGCC rules were observed at the time of the inspection of the frack operation nor in the surrounding neighborhood.](#)

[All information reviewed and site inspection information were submitted to the complaint specialist for further review.](#)

Corrective Action:

Date:

| Well Stimulation | | | |
|------------------------------|--|---------------------------------------|--|
| Stimulation Company: Liberty | | Stimulation Type: HYDRAULIC FRAC | |
| Other: | | | |
| Maximum Casing Recorded: PSI | | Tubing: | |
| Surface: | | Intermediate: | |
| Production: | | Instantaneous Shut-In Pressure (ISIP) | |
| Bradenhead Psi: | | Frac Flow Back: Fluid: Gas: | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 453233 | Type: | WELL | API Number: | 123-45993 | Status: | DG | Insp. Status: | WO |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 453234 | Type: | WELL | API Number: | 123-45994 | Status: | DG | Insp. Status: | WO |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|