

Inspection Photos
Location Name: Beaver Creek 0881 1-3H34
API: 05-057-06602



Photo 1. Overview of location taken at entrance facing northeast.

Inspection Photos
Location Name: Beaver Creek 0881 1-3H34
API: 05-057-06093



Photo 2. Rathole open at wellhead.



Photo 3. No wellhead sign, no emergency number on location.