

# *Inspection Photos*

*API#081-06814*

*Operator: Carmack Resources*

*Inspection Number: 674104483*

*Inspection Date: 7/7/2018*





Photo#1:  
View from center of Location to Northwest.

June 7, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Carmack Resources PA Anak #1 API#081-06814



Photo#2:

View over one of concentrated thistle populations; insert of Thistle rosette.

June 7, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Carmack Resources PA Anak #1 API#081-06814



Photo#3:

View over one of concentrated thistle populations; insert of Thistle rosette.

June 7, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Carmack Resources PA Anak #1 API#081-06814