

Inspection Photos

Loc#313140

Operator: Santa Fe Natural Resources

Inspection Number: 674104493

Inspection Date: 6/18/2018





Photo#1:
Overview of Location to Northeast.

June 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Natural Res JSR Loc#313140



Photo#2:

Thousands of Scotch thistle rosettes are emerging in one depression area on North Fill Slope side of Location.

June 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Natural Res JSR Loc#313140



Photo#3:

Scotch Thistle established within the 25 ft. Safety Zone of Well Head.

June 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Natural Res JSR Loc#313140



Photo#4:
Metal & Thistle Debris in Pad area.

June 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Natural Res JSR Loc#313140



Photo#5:

Portions of Access Road road are a monoculture of Cheatgrass (C List Noxious weed) interspersed with Russian thistle..

June 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Natural Res JSR Loc#313140



Photo#6:
Noxious weeds have migrated off location & infected adjacent rangeland.

June 18, 2018