

**Inspection Photo
Kaufman 41A-25-692
API # 045-19689
Inspection # 689301372**



Location Photo #1




Location Photo #2,

**Inspection Photo
Kaufman 41A-25-692
API # 045-19689
Inspection # 689301372**



Location Photo #3

**Inspection Photo
Kaufman 41A-25-692
API # 045-19689
Inspection # 689301372**



Location Photo #4, Missing and non-legible tank information

Location Photo #5, Stained material in battery containment

**Inspection Photo
Kaufman 41A-25-692
API # 045-19689
Inspection # 689301372**



Location Photo #6, Small drip on a flowline from a separator



Location Photo #7, Small drip on a flowline