

Final Reclamation Inspection

June 20, 2018

Operator: PDC ENERGY INC - 69175

API: 05-001-08989

Inspection Document #: 682403715

Adams County, CO

SENW Section 15 T1S R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: CALDWELL FARMS #1-A

API: 05-001-08989



Photo 1. Photo taken from the start of the access road, facing East. Appears location was recently mowed. Access road and well location have desirable germination of vegetation but noxious weeds (Canada thistle, Puncture vine, and Cheatgrass) were observed throughout portions of the disturbance area. At a minimum, Operator shall control Canada thistle, as it is a List B Colorado noxious weed. Mowing operations would not be considered a long term weed control management practice for Canada thistle.



Photo 2. Photo taken along a portion of the disturbance area, illustrating Canada thistle that has been recently mowed.

Inspection Photos
Location Name: CALDWELL FARMS #1-A
API: 05-001-08989



Photo 3. Photo taken from the well location, facing West. See comments under Photo 1.



Photo 4. Reference photo taken south of the well location, facing West. Access road and well location will remain IN-PROCESS has vegetation is not reflective of reference area vegetative levels.