

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2018

Submitted Date:

06/26/2018

Document Number:

690001799

**FIELD INSPECTION FORM**

Loc ID 330386 Inspector Name: Carlile, Craig On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Findings:**

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251204	WELL	PR	08/01/2017	GW	123-19007	HSR-FOSTER 4-35	PR

**General Comment:**

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Barb Wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barb Wire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Barb Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		

Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared with crude oil tank.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.188850,-104.635760
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	Ignitor/Combustor
------	-------------------

Comment:		
Corrective Action:	Date:	

**Inspected Facilities**

Facility ID: 251204 Type: WELL API Number: 123-19007 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR](#)

Corrective Action:

Date:

**BradenHead**

Comment: [Bradenhead plumbed to surface.](#)

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<a href="#">Routine inspection.</a>	carlilec	06/26/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690001800	Photos	<a href="#">330386.pdf</a>