

Final Reclamation Inspection

June 20, 2018

Operator: BURLINGTON RESOURCES OIL & GAS LP- 26580

API: 05-005-07232

Inspection Document #: 682403726

Arapahoe County, CO

NESE Section 5 T4S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Parachute 4-65 5-6 #3H
API: 05-005-07232



Photo 1. Photo taken east of the location, facing West. Well location was not constructed at the proposed location based off field observations.