

TR 33-27-597
Api# 05-045-10600
Inspection # 689701531



Location photo.

TR 33-27-597
Api# 05-045-10600
Inspection # 689701531



Tear in netting at post.

TR 33-27-597
Api# 05-045-10600
Inspection # 689701531



Tear in netting at post.

TR 33-27-597
Api# 05-045-10600
Inspection # 689701531



Tear in netting at post.

TR 33-27-597
Api# 05-045-10600
Inspection # 689701531



Gap along bottom of netting.