

**Inspection Photo**  
**COOK RW 7-33**  
**API # 045-06883**  
**Inspection # 689301407**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo  
COOK RW 7-33  
API # 045-06883  
Inspection # 689301407**



**Location Photo #3**



**Location Photo #4, ECB on site not hooked up**



**Inspection Photo**  
**COOK RW 7-33**  
**API # 045-06883**  
**Inspection # 689301407**



**Location Photo #5**



**Location Photo #6**



**Inspection Photo  
COOK RW 7-33  
API # 045-06883  
Inspection # 689301407**



**Location Photo #7, weeds near entrance of location**



**Location Photo #8, weeds near Wellheads**

**Inspection Photo**  
**COOK RW 7-33**  
**API # 045-06883**  
**Inspection # 689301407**



**Location Photo #9, weeds near Methanol tank**