

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/19/2018

Submitted Date:

06/28/2018

Document Number:

680303415

FIELD INSPECTION FORM

Loc ID 313979 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10657
Name of Operator: PCR OPERATING LLC
Address: 4040 BROADWAY STREET #510
City: SAN ANTONIO State: TX Zip: 78209

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Wehrer, Gene	(970) 380-4860	gwehrer@passcreekresources.com	Adena Inspections
Quint, Craig		craig.quint@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
227414	WELL	TA	05/03/1990	ERIW	087-60019	ADENA J SAND UNIT W-13	TA

General Comment:

UIC Routine Inspection - FIR - 2018 UIC list shows well due for MIT, UIC/MIT (5 yr.) performed on 4/21/2017 Doc# 680301880 (Form 21 attached). Results of 2018 UIC Routine - SATISFACTORY

Location			
Lease Road:			
Type	Access		
comment:	Two track - grassland		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Other	# 0		corrective date
Comment:	No change in equipment inventoried		
Corrective Action:		Date:	
Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 227414 Type: WELL API Number: 087-60019 Status: TA Insp. Status: TA

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 0 Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: JSND
 TC: Pressure or inches of Hg 330 Previous Test Pressure _____ Last MIT: 01/06/2012
 Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: No problems found

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: UIC Routine

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: [Use BMP's](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT