

Location Name: Croissant #1 API: 05-123-21426, Spill Id 454027 Inspection Date: 6/28/2018



Photo 1 – Croissant #1 wellhead release, spill ID 454027, backfilled in process. Looking north.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Croissant #1 API: 05-123-21426, Spill Id 454027 Inspection Date: 6/28/2018



Photo 1 – Croissant #1 wellhead release, spill ID 454027, backfilled in process. Looking northeast.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources