



**Photo 1. View of the project area from the western corner facing center.**



**Photo 2. View of the southwestern portion of the project area from the western corner facing southeastward. Revegetation is largely weedy, comprised with cheatgrass (*Bromus tectorum*). Some desirable vegetation is established and comprised of western wheatgrass (*Pascoopyrum smithii*), intermediate wheagrass (*Thinopyron intermedium*), and crested wheatgrass (*Agropyron cristatum*).**



**Photo 3. View of the western portion of the project area from the western corner facing northeastward.**



**Photo 4. View of area in the northeaster portion of the project area where there is Russian thistle debris and rilling from stormwater runoff from the well pad.**



Photo 5. View of musk thistle (*Carduus nutans*) within the interim reclamation area.