

**Inspection Photo  
Left Hand Fed CA 3  
API # 045-20572  
Inspection # 689301417**



**Location Photo #1**



**Location Photo #2**



**Inspection Photo**  
**Left Hand Fed CA 3**  
**API # 045-20572**  
**Inspection # 689301417**



**Location Photo #2, Stained Rock near tank valves**



**Location Photo #4, Stained Rock near tank valves**



**Inspection Photo**  
**Left Hand Fed CA 3**  
**API # 045-20572**  
**Inspection # 689301417**



**Location Photo #5, Stained rock in containment**



**Location Photo #6, Stained rock in containment**



**Inspection Photo  
Left Hand Fed CA 3  
API # 045-20572  
Inspection # 689301417**



**Location Photo #7, Stained rock in containment**



**Location Photo #8, Stained rock in containment under tank heater.**