

Inspection Photos
 Location Name: PCW 23-9
 Facility ID: 217548



Colorado Oil & Gas Conservation Commission
 37.09681, -104.68103, 1931.0m, 26°
 2018/06/29 10:28:59

Photo 1. Wellhead/packing leak



Colorado Oil & Gas Conservation Commission
 37.00668, -104.48747, 237°
 2018/06/29 10:28:24

Photo 2. Calibration out of date

Inspection Photos
Location Name: PCW 23-9
Facility ID: 217548



Photo 3. trash



Photo 4. Unused equipment stored on location.