



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western portion of the project area from the northwestern corner facing southward. Revegetation is progressing with grasses such as western wheatgrass (*Pascoopyrum smithii*) and smooth brome (*Bromus inermis*).



Photo 3. View of Russian knapweed (*Rhaponticum repens*) infestation within the northwestern portion of the project area.



Photo 4. View of debris within the interim reclamation area.