



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is progressing and comprised of grasses and shrubs such as western wheatgrass (*Pascoopyrum smithii*), smooth brome (*Bromus inermis*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3. View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4. View of diversion in the southwestern portion of the project area facing westward. Diversion appears to be functioning at this time.



Photo 5. View of unmarked rig anchor within the western portion of the working area.