

**DOE 1 M-35 Pad**  
**Location Id. 335148**  
**Inspection # 689701555**



**Battery sign is weathered.**

**DOE 1 M-35 Pad**  
**Location Id. 335148**  
**Inspection # 689701555**



**Location photo.**



**DOE 1 M-35 Pad  
Location Id. 335148  
Inspection # 689701555**



**Washing check dam in north east corner of location.**



**DOE 1 M-35 Pad**  
**Location Id. 335148**  
**Inspection # 689701555**



**Washing check dam in north east corner of location.**



**DOE 1 M-35 Pad**  
**Location Id. 335148**  
**Inspection # 689701555**



**Location berm on east edge is washing.**

**DOE 1 M-35 Pad**  
**Location Id. 335148**  
**Inspection # 689701555**



**Washing ruts and rills on access road.**



**DOE 1 M-35 Pad**  
**Location Id. 335148**  
**Inspection # 689701555**



**Washed hole at switch back (39.47929 -108.06580)**





**DOE 1 M-35 Pad  
Location Id. 335148  
Inspection # 689701555**



**Washed hole at switch back (39.47929 -108.06580)**





**DOE 1 M-35 Pad**  
**Location Id. 335148**  
**Inspection # 689701555**



**Sediment build up in ditch**



**Sediment build up in ditch**



**DOE 1 M-35 Pad**  
**Location Id. 335148**  
**Inspection # 689701555**



**Washing of shoulder of access road. (39.48023 -108.06867)**

**Washing of shoulder of access road. (39.48023 -108.06867)**



**DOE 1 M-35 Pad**  
**Location Id. 335148**  
**Inspection # 689701555**



**Washing of shoulder of access road. (39.48023 -108.06867)**



**Washing of shoulder of access road. (39.48023 -108.06867)**