



**Photo 1. View of the project area from the southwestern corner facing center.**





**Photo 2. View of the western portion of the project area from the southwestern corner facing northward. Revegetation is progressing and comprised of grasses and shrubs such as western wheatgrass (*Pascoopyrum smithii*), smooth brome (*Bromus inermis*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).**





**Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward.**





**Photo 4. View of unmarked rig anchor within the western portion of the project area.**





**Photo 5. View area in the western portion of the working area where concentrated stormwater becomes concentrated and is eroding the western portion of the project area.**