

Inspection Photos
Well Name: SSR 9-17
Location ID: 312606



Photo 1. Well plate.



Photo 2. Excavation around cut off wellhead.