

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/28/2018

Submitted Date:

07/02/2018

Document Number:

689401428

FIELD INSPECTION FORM

Loc ID 312604 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Reid, Jordan	(970) 563-4000	maralextechjr@gmail.com	All Inspections
Engineering		dnr_cogccengineering@state.co.us	All Engineering
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	All Inspections
Graves, Jim	(970) 858-8550	mrinc20@qwestoffice.net	Operation Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222003	WELL	SI	10/01/1995	GW	077-08605	SOUTH SHALE RIDGE 16-16	PA

General Comment:

[This well is listed on AOC 1V-609](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type UNUSED EQUIPMENT

Comment: Equipment has been removed from site.

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 222003 Type: WELL API Number: 077-08605 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: Well has been plugged. No form 6(S) in well file. Cap has been welded on.

Corrective Action:

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689401429	SSR 16-16 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4511796