



**Photo 1. View of the project area from the southwestern corner facing center.**



Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation is progressing and comprised of grasses and shrubs such as western wheatgrass (*Pascoopyrum smithii*), smooth brome (*Bromus inermis*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).



**Photo 3. View of the western portion of the project area from the southwestern corner facing northward.**



**Photo 4. View of unmarked rig anchor within the western portion of the project area.**



**Photo 5. View area in the northjwestern portion of the working area where concentrated stormwater becomes flows off of the northwestern corner of the working area.**