

# Final Reclamation Inspection

June 27, 2018

Operator: SRC ENERGY INC- #10311

API: 05-123-26506

Inspection Document #: 682403743

Weld County, CO

NESE Section 2 T5N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Aufrecht #N02-09  
API: 05-123-26506



**Photo 1.** Photo taken from the well location, facing West. Unable to find evidence of oil and gas activities and/or disturbances. Well location and access road appear reflective of reference crop areas.



**Photo 2.** Photo taken from the well location, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: Aufrecht #N02-09  
API: 05-123-26506



**Photo 3.** Photo taken from the well location, facing East. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: Aufrecht #N02-09  
API: 05-123-26506



**Photo 3.** Reference photo taken southwest of the well location, facing North. Well location and access road appear reflective of reference crop areas.