

Inspection Photos

API#029-06092

Operator: Gunnison Energy

Inspection Number: 674104510

Inspection Date: 6/25/2018





Photo#1:
View to Northwest along Access road into Location.

June 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gunnison Energy PA Scott API#029-06092



Photo#2:
Overview of Location to North.

June 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gunnison Energy PA Scott API#029-06092



Photo#3:

Evidence of the Well is still visible, casing / fitting, day lighting approximately 36" above ground.

June 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gunnison Energy PA Scott API#029-06092



Photo#4:

Wood, metal, liner, materials, down fencing Debris as well as Guy anchors remain on Site.



Photo#5:

June 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gunnison Energy PA Scott API#029-06092



Photo#6:

Wood, metal, liner, materials, down fencing Debris as well as Guy anchors remain on Site..

June 25, 2018

Photo#7:



Photo#8:

Wood, metal, liner, materials, down fencing Debris as well as Guy anchors remain on Site.



Photo#9:

June 25, 2018



Photo#10:
B List, Noxious weeds, Thistle, Knapweed and C List, Common Mullein were noted on Site.



Photo#11:

June 25, 2018