

Inspection Photos

Location Name: Swafford - 65N67W / 11NENE

Location #: 330117



Photo #1

Swafford 11-11 (API 05-123-18430) wellhead

Unused equipment has been removed. Weeds sprayed.

Emergency contact info is accurate.



Photo #2

Artist 11-12, Swafford 11-11 Battery

