

Inspection Photos

Location Name: Artist - 65N67W / 11NWNE

Location #: 330118



Photo #1

Artist 11-12 (API 05-123-18431) wellhead

Weeds & unused equipment have been removed.



Photo #2

Artist 11-12, Swafford 11-11 Battery

Gas meter house door has been installed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Artist - 65N67W / 11NWNE

Location #: 330118



Photo #3

Meter House door is missing
facing W

Mechanical Conditions



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources