

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/03/2018

Submitted Date:

07/03/2018

Document Number:

689301453**FIELD INSPECTION FORM**
 Loc ID 334930 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerus oilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258479	WELL	SI	10/01/2015	GW	045-07641	CEDAR SPRINGS RANCH 2-11 (K2W)	TA
259954	WELL	PR	01/20/2005	GW	045-07803	CEDAR SPRINGS RANCH 2-11 (K2W)	PR

General Comment:[Routine Follow Up Inspection](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment:	Centralized Battery					
Corrective Action:		Date:				

Paint

Condition	Adequate	
Other (Content)	Methanol Tank	

Inspector Name: Holtz, Darin

Other (Capacity) 500 gallon	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 258479 Type: WELL API Number: 045-07641 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____Facility ID: 259954 Type: WELL API Number: 045-07803 Status: PR Insp. Status: PR**Producing Well**Comment: [Well Producing on plunger lift](#)Corrective Action: Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Seeding						
Berms						
		Compaction				
Slope Roughening						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301454	Inspection Photo 689301454	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4513345