

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/03/2018

Submitted Date:

07/04/2018

Document Number:

680403080

FIELD INSPECTION FORM

Loc ID 315664 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 100 CHEVRON RD
City: RANGELY State: CO Zip: 81648

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Peterson, Diane	970-675-3842	dlpe@chevron.com	Regulatory Specialist
Koehler, Bob		bob.koehler@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231285	WELL	SI	01/12/2018	OW	103-08955	EMERALD 79X	SI

General Comment:

[UIC-MIT. New well permit.](#)

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action			Date:
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 231285 Type: WELL API Number: 103-08955 Status: SI Insp. Status: SI

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: <u>WEBR</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>04/13/2011</u>
			AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: Verification of Repairs Tbg psi: 0 Csg psi: 2350 BH psi: 0

Insp. Status: Pass

Comment: UIC-MIT. Initial MIT prior to injectivity test for new well. Wellwork done to convert Weber fm. producer to Navajo fm. disposal well. Pressure well to 2350 psi. Hold for 15 min. Final pressure 2350 psi. 0 psi loss. OK. Test witnessed by COGCC using chart on truck.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	Self Inspection	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT