

Inspection Photos

Loc#312741

Operator: Laramie

Inspection Number: 674104524

Inspection Date: 6/28/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View over Location from Entry to Northeast.

June 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Loc#312741



Photo#2:

Areas no longer needed for Use / Production have not been reclaimed for Interim Reclamation.

June 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Loc#312741



Photo#3:
New growth of Noxious Weeds was noted on Location.



Photo#4:

June 28, 2018