

Inspection Photos
Location Name: Putman 41-18
Location ID: 319787



Photo#1 Production Tank/Concrete Pit



Photo#2 Equipment

Inspection Photos
Location Name: Putman 41-18
Location ID: 319787



Photo#3 Equipment



Photo#4 Wellhead

Inspection Photos
Location Name: Putman 41-18
Location ID: 319787



Photo#5 Barrel full of trash next to wellhead



Photo#6 Stack of tires on location

Inspection Photos
Location Name: Putman 41-18
Location ID: 319787



Tuesday, July 3, 2018 11:40:03
25100 E 152nd Ave Brighton CO 80603
United States

Photo#7 Uncontrolled weeds




Tuesday, July 3, 2018 11:40:27
25100 E 152nd Ave Brighton CO 80603
United States

Photo#8 Tank with lid laying on ground/NO labels

Inspection Photos
Location Name: Putman 41-18
Location ID: 319787



Photo#9 Equipment



Photo#10 Stained soil

Inspection Photos
Location Name: Putman 41-18
Location ID: 319787



Photo#11 More uncontrolled Weeds inside berm



Photo#12 Lease road in disrepair