

Inspection Photos

Loc#334463

Operator: Laramie

Inspection Number: 674104528

Inspection Date: 6/28/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View over Location from Entry to Southwest.

June 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie N Vega Loc#334463



Photo#2:

Areas no longer needed for Use / Production have not been reclaimed for Interim Reclamation.
View to Southeast from top of what is identified as Dirt Stockpile in Location diagram.

June 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie N Vega Loc#334463



Photo#3:
Two anchors noted run over & not marked..



Photo#4:

June 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie N Vega Loc#334463



Photo#5:
Liner has become debris



Photo#6:
One Sediment trap is full to drain out level.

June 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie N Vega Loc#334463



Photo#7: Aerial 2009 COGCC Maps

Photo#8: Aerial 2017 COGCC Maps

Areas no longer needed for Use have not been reclaimed for Interim Reclamation.

June 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie N Vega Loc#334463