

Inspection Photos
Location Name: Near 3-28
Spill/Release ID: #455436
Inspection Date: June 20, 2018



Photo #1 – View of fenced flowline excavation from inside of intermittent stream, looking NE.



Photo #2 – View of flowline excavation and fluid flow path from inside of intermittent stream. Yellow notebook is located at approximate terminus of released fluid flow.

Inspection Photos
Location Name: Near 3-28
Spill/Release ID: #455436
Inspection Date: June 20, 2018



**Photo #3 – View into intermittent drainage, looking NE.
Yellow notebook is located at approximate terminus of
released fluid flow.**



**Photo #4 - View of flowline excavation and BLM Right-of-Way,
looking NE.**