



Form Information

| | |
|----------------------|--|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Reclamation Tablet (reclamationtablet) |
| Submission Date: | Jul 3, 2018 12:22:02 PM MDT |
| Server Receive Date: | Jul 3, 2018 12:22:11 PM MDT |
| Reference Number: | 20180703-1882182701 |
| Location: | 1295 Co Rd 221, Durango, CO 81303, USA |
| | Jul 3, 2018 12:21:43 PM MDT [View Map] |

Information

| | |
|-----------------|---|
| Name | reclamationtablet |
| Date | Jul 3, 2018 |
| Well Name | COLE, JAMES GAS UNIT A 1 |
| API Number | 50670772000 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Compliance Inspection Actions Other Replaced/Repaired Well Sign |

Picture West to East



Additional photos



Additional photos



Additional photos



Completed work description

marked 3 dead man anchors and replaced 1 well sign