

# Inspection Photos

07/03/2018

Operator: PCR OPERATING LLC - 10657

Location ID: 314070

Inspection Doc. Number: 682503546

Phillips County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the well location, facing west. Photo shows location within a fallow crop field. A follow-up inspection will need to be conducted when vegetation is established to determine compliance with reclamation standards and requirements