

Inspection Photos
Location Name: Villard 1-27
API: 05-081-06329



Photo 1. Overview of location taken at entrance facing southwest.

Inspection Photos
Location Name: Villard 1-27
API: 05-081-06329



Photo 2. Unmarked riser not LOTO.



Photo 3. No capacity on produced water tank.