

Inspection Photos
Location Name: Maudlin Gulch Unit 2
API: 05-081-05065



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. Stained soil at wellhead.